

	Meyer first upgrades after purchase by Mr Meyer, 2013	
	74642 miles in, 74644 miles out	
	Updated worksheet 12/15/13-Completed 12/19/13	
	Customer visited and selected and approved the following repairs:	
	labor \$110 per hour	Robert Meyer red bug eye
75	Car purchased on Ebay, Vehicle inspection	
165	change all four shocks and bushings as needed, labor 1.5	
369.99	Front shocks 184.95 each	
349.90	rear shocks 174.95 each	
150	Dash top piece vinyl covered	
450	Powdercoat 3 cockpit pieces, replace screws with stainless oval head	
100	Install customer supplied dash mirror-price depends on thread condition, no screws provided-sheet metal screws had been used and damaged threads, remove windshield frame, tap holes, install customer supplied mirror, replace windshield frame	
50	steering wheel play-address loose wheel. Steering rack loose, properly shim to locate and secure rack	
75	Felt steering column bushing worn, remove steering column, replace upper and lower felt bushings, repair horn push, horn bezel screws missing, modify horn brush so horn push stays in place and horn operates properly	
100	Alignment off, align and align steering wheel which was not straight when car arrived	
50	choke not locking labor to install new choke cable, lubricate and adjust mechanism	
19.95	new choke cable twist and lock type	
250	Tune is terrible, very lean, needs choke pulled to run, even as warming up- estimate \$275—remove air filters, adjust mixture, synch carbs, set timing, check plugs, tune, run test, throttle response better now. Note throttle shafts worn and need to be re-bushed.	
35	Sender reading backwards-inspect and advise only if simple.Diagnose reverse reading fuel sender, disconnect sender, swing new sender to check gauge and system integrity, new sender operates gauge perfectly, new sender needed, need to drain and drop tank to change sender	
n/c	Antifreeze check for optimum protection	50below
35	inspect rear brakes, rear seals-remove drums, clean right rear back plate, drum and shoes, some weeping, tighten banjo bolt and brake line, watch for future leaks	
8	Install correct shock bolts-parts	
10	Hydraulic fluid to bleed and fill once slave changed	
35.80	Chrome thumb Screws Sidecurtain 8.95 each	
19.95	Shipping of parts from suppliers	
	Possible ship to westport when done	
150	Heater valve leaking, replace with new valve and base, gaskets and sealing rings	
200	Slave cylinder leaking, replace with uprated British unit	
30	spare tire tie down straps installed	
5	antifreeze, refill after changing heater valve	
25	Glue/reattach door seal gasket on driver door	
50	remove carb tops, float bowls full of rusty fuel, clean out bowls, change fuel filter (parts included), new fuel filter shows rust immediately, this issue will cause car to die when filter clogs next time.	addressed on line below

525	drain, remove and replace fuel tank with new unit, paint tank exterior, replace sender with deluxe unit that works and won't sink, as well as fit gasket that won't leak when tank full. Parts and labor to remove and replace tank and sender	
20	Remove and replace fuel neck gasket, parts and labor	
3353.59	Total due	
	Paid check 3250 \$3388.59, zero balance	
	Notes:	
	throttle shafts worn	
	king pin bushings worn	
	oil pressure gauge line is ancient and should be changed	
	74644 miles out- now 74963	
	Thank you and congratulations!	