

Calvin Consign for Brad Phillips

Bugeyeguys
 59 N Harbor St
 Branford, CT 06405
bugeyeguys.com
 203-208-0980
customercare@bugeyeguys.com

Automobile Restoration Build Sheet
 Shop Rate \$175/hr

	Car arrived at our shop in April of 2026	
612.5	5/4/26 Terry - Traced coolant leak to cylinder head gasket. Removed radiator, carbs and intake, disconnect exhaust. Removed cylinder head and cleaned block and cylinder head surfaces. Cylinders and head look good! Installed new cylinder head studs and payen composite gasket.	
26.29	head gasket set	
74.95	cylinder head studs	
23.50	stud washers and nuts	
1400	5/5/26 Terry - Re install cylinder head with all new gaskets and seals for exhaust and intake manifold. Replaced side cover gaskets with upgraded neoprene gaskets. Install mechanical fuel pump block off plate. Install electric fuel pump in rear of car for better reliability and wire to harness. Install new under car fuel line with all clamps and clips to secure in place. Install fuel filter under hood at carburetors. Install new spark plugs. Install all new coolant hoses under hood. Install new heater valve kit with gaskets and hardware. Install new thermostat housing, 160 thermostat, gaskets and hardware. Drain rear differential housing and remove differential. Strip off rear brakes for later re use. Replace pinion seal, rear hubs seals and gaskets and differential gasket. Remove fuel tank to reseal sender gasket with ethanol proof viton gasket. Metal float is present	
9.95	side cover gaskets	
10.69	fuel pump block off kit	
13.95	spark plugs	
139.95	electric fuel pump kit	
79.95	body fuel line kit	
66.75	heater valve kit	
66.50	radiator hose kit	
49.52	thermostat housing, gasket, thermostat and hardware	
7.14	exhaust manifold clamp	
2.72	pinion seal	
4.95	differential seal	
12.95	rear hub seal kit	
5.95	viton gasket for sender	
1400	5/6/26 Terry - Strip off front suspension, strip out metal brake lines from entire car for replacement. Found damaged/worn passenger side control arm mounting brackets and repaired (see below on next line) Re install front control arms with new bushings, existing bolts and new pivot pins. Install new front shock bushings and shock absorber bump stops. Strip down front brakes and front hubs. Shim king pins on both sides to remove play and install new tapered set of front wheel bearings into existing wheel hubs. Replace all four front brake wheel cylinders, refit brake shoes, hardware and brake drums. Replaced rear wheel cylinders with existing brake shoes as they are already mated to drums, hardware, adjusters and drums. Remove pedal box and master cylinder assembly from car.	
337.5	5/6/26 Ken - Passenger lower control arm mounts on frame are oval shaped and damaged from previous repair by prior owner. Welded new material in place and re drilled holes to proper size. Paint repaired area to match so that it looks like new.	
294.55	complete brake line kit	

Bugeyeguys
 59 N Harbor St
 Branford, CT 06405
bugeyeguys.com
 203-208-0980
customercare@bugeyeguys.com

Automobile Restoration Build Sheet
 Shop Rate \$175/hr

183.98	2 rear wheel cylinders (all premium type)	
180.92	4 front wheel cylinders	
15.92	lower control arm bushings	
37.98	pivot pin assembly control arm	
14.71	front shock bushings	
115.71	tapered wheel bearing set	
4.95	shock bump stops	
1400	5/7/26 Terry - Fill differential with new oil. Complete brake line and clutch line installation, install new clutch slave cylinder. Install pedal box back into car with new brake master, pedal pads and return springs. Install new rubber brake lines. Bleed hydraulic system of car. Complete front suspension installation, with new tire rod boots. Install new battery and both positive and negative battery cables. Replace distributor cap, rotor, ignition points and condenser.	
18.5	80W90 oil	
214.99	master cylinder slave cylinder kit	
61.95	rubber brake line kit	
6.3	pedal pads	
6.78	master return springs	
9.24	tie rod end boots	
150	battery	
16.95	negative battery cable	
19.95	positive battery cable	
29.11	cap and rotor	
19.98	points and condensor	
11.95	brake fluid	
1.25	clutch slave clevis pin	
1225	5/8/26 Terry - Install new battery hold down kit, re install heater back into car, re install radiator, connect all new hoses, fill coolant system. Clean up intake manifold and carburetors and reinstall onto engine, connect throttle and choke cables, Connect fuel line with new filter. Install new ground strap under car. Install new ignition switch with guillotine to properly secure ignition switch, clean up wiring under dash, fixing connections to heat and wiper switches. Secure combo gauge in place, secure horn push and add new horn brush and clips for horn push.	
24.45	battery hold down kit	
34.99	engine ground strap	
231.99	ignition switch with guillotine, all new	
28.99	horn brush	
24.95	coolant	
656.25	5/11/26 Terry - Install and seal new fuel tank sender, pressure test and re install into car. Install new fuel tank pickup line. Install remanufactured premium rear shock absorbers with new dog bone links. Re install air cleaners. Tune carburetors and set ignition timing.	
79.99	fuel pickup line	
7.95	fuel tank mounting strips	

Bugeyeguys
 59 N Harbor St
 Branford, CT 06405
bugeyeguys.com
 203-208-0980
customercare@bugeyeguys.com

Automobile Restoration Build Sheet
 Shop Rate \$175/hr

78.95	fuel level sender	
399.95	premium rear shocks	
77.82	rear dog bone shock links	
437.5	5/12/26 Ken - Pulled up old mat material and cleaned old glue off footwell crossmembers. Fabricated new ribbed mats for front crossmember and adhered into place.	
65	ribbed mat material, adhesive	
175	5/14/26 Terry - Speedo inop, drive cable to short. Swapped for used longer cable from stock. Replaced fuse block, poor connection, fuel pump cutting out. Adjust steering wheel position.	
17.87	fuse block	
49.95	Custom matched spray touch up paint to refinish suspension repair area with correct color	
107.78	shop supplies - solvents, fluids, rags misc. hardware etc.	
10885.76	total build cost to bring car to the next level	