

Table 1

22,995	Sale of the MGBGT	
0	CC deposit- We did not charge your card, since you are sending an ACH payment, no need for a cc deposit, 4-29-24	
-23,000	Wire transfer received 4/30/24	
87.5	4-30-24 Ken repair storage compartment basket	
875	5-8-24 Ted disconnect battery, drain fluids from radiator/engine/trans, remove driveshaft, prep for engine/trans removal.	
1487.5	5-10-24 Ted remove accessories from engine in order to remove engine & trans as an assembly (exhaust system, intake and exhaust manifolds, etc.), remove transmission mount and cross member, remove front bumper (for better access in order to lift engine), remove engine and transmission from car, disassemble on bench, remove old pilot bushing and press in new one, bolt on pressure plate and new clutch disc.	
1575	5-13-24 Ted bolt together engine and 5 speed transmission on the bench, remove the leaking steering rack, remove slave cylinder and slave cylinder line, fabricate custom GPS speed box bracket and mount the box under the dashboard against the firewall, install new motor mounts on engine and set engine/transmission as an assembly back into engine bay, install driveshaft and grease the u-joints, mount new thermostat and gasket, run new slave cylinder line.	
5995	5 speed Miata conversion kit (received 5/3/24)	
524.95	speedbox speedo GPS driver	
179	Shipping 5 speed kit from europe	
28	new motor mounts	
9.99	Manifold gasket	
8.95	Thermostat (160°) & gasket	
4.74	Manifold to carburetor gaskets (6)	
2100	5-14-24 Ted begin re-installing accessories in the engine compartment, prep carburetor heat shield for re-installation, inspect carburetors - found rear carburetor body has been rubbing against the throttle cable for an extended amount of time and a groove has been worn into the body of the float chamber - not leaking now but will most likely leak in the future, inspect throttle shafts and there is play in the shafts - Gordon says good to rebuild carbs so strip carburetors and send out bodies to be re-bushed. Prep exhaust manifold for re-installation - (extra labor needed - studs stretched and one broken on manifold upon removal from lower section of exhaust, Ken had to weld on nuts in order to remove broken/damaged studs and re-install) , fabricate two new brackets to mount the hydraulic slave line, re-install oil filter adapter with new filter, install new oil pressure gauge line, install generator, radiator and radiator supports, radiator and heater hoses, fill cooling system with antifreeze, remove transmission tunnel to properly secure shift lever.	
8	Heater hose	
9.95	Spin on oil filter	
0.99	Oil filter housing o-ring	
16.99	Oil pressure gauge line	
15.54	Exhaust manifold lower studs (6)	
4.74	Exhaust manifold lower stud brass nuts (6)	
262.5	5-14-24 Nick dismount tires, mount and balance four wheels with new tubes	
832	four 180/14 michelins (258 each)-current tires were 2015	
150	tire shipping	
80	new tubes	
56	New rim bands	
16	Tire disposal fee	
1400	5-15-24 Ted replace positive battery cable, install new end on negative battery cable, install exhaust system, replace cracked rear check straps, wire in GPS box for speedometer, drill and mount battery, and install battery hold down, install steering rack with new tie rod ends, tighten the steering column	

7.98	Exhaust donuts (2)	
18.95	Positive battery cable	
18.99	Negative battery cable end	
10.99	Battery hold down	
370	Rack & pinion + install kit-new steering rack	
28.99	Tie rod ends	
6.50	Tie rod end jam nuts	
11.8	Rear check straps	
743.75	5-28-24 Terry clean parts and reassemble/rebuilt carburetors after receiving the freshly bushed bodies back, run and tune the car, replace the throttle cable and choke cable, install a new fuel filter in the engine bay and replace fuel and breather hoses.	
199.99	Carburetor float chamber (1 replacement)	
475	Re-bush carburetor bodies	
219.99	Carburetor rebuild kit	
9.99	Throttle cable	
14.95	Choke cable	
8.95	Fuel filter	
10	Hoses	
1443.75	5-29/30-24 Ted install GPS antenna for the speedometer, re-install shift tower, install air cleaners, replace the overflow hose - old hose was cracked and not working properly, remove the valve cover and adjust the valves, adjust the steering, install the front bumper back on the car, check all fluids, check and adjust toe, install battery terminal covers, install hood and adjust fitment, check all lights, install the battery cover, install the rear seat, tighten the steering wheel.	
5	Overflow hose	
2.99	Valve cover gasket	
1.98	Valve cover bushings	
3.98	Air cleaner to carburetor gaskets	
8	Battery terminal covers	
393.75	6-3-24 Ted lower the idle, mount the GPS antenna under the dashboard, remove, disassemble and repair the horn button, temperature control cable hitting bottom of the dashboard - install spacer. Test drive car, found GPS not initializing, need to install antenna on top of dashboard, install antenna on top of dashboard.	
175	6-4-24 Ken adjust door hinges and latches	
395	Remove, send out and manage repair of tachometer, now rebuilt to operate on positive ground and electronic ignition	
203.15	shop supplies	
35	parts shipping and gauge shipping to MN	
20309.61	total due	
1575	shipping to MN	
21884.61	total due with shipping	
-21884.61	Wire received 6/10/24	
	NOTES	