

|               |   |                                      |
|---------------|---|--------------------------------------|
|               | 1966 MGB GT replace interior and mechanical refresh 2022  |                                      |
|               | Delivered friday 3-25-22  |                                      |
|               | 45424 miles out 5-22-22   |                                      |
| <b>500</b>    | 3-28-22 Ken, remove trim pieces, remove headliner, remove front and rear seats for recover  |                                      |
| <b>250</b>    | 3-29-22 Ken vacuum interior thoroughly, remove rear seat bottom and back  |                                      |
| <b>187.50</b> | remove rear seat for recover, attempt to clean rubber floor mats-instead, we chose to remove them and replace sill pads   |                                      |
| <b>218.75</b> | 4/4/22 Lay out vinyl and began prep for headliner and vinyl, 1.75   |                                      |
| <b>625</b>    | 4/5/22 Ken put in headliner and covered side trim pieces, 5 hours   |                                      |
| <b>187.50</b> | 4/6/22 Ken install newly recovered trim pieces surrounding headliner, 1.5 hours   |                                      |
| <b>875</b>    | 4-18-22 Ken remove carpet and panels, start carpet install  |                                      |
| <b>812.50</b> | 4-20-22 6.5 Ken rear seat build and b pillar panel modifications to get them to fit   |                                      |
| <b>875</b>    | 4-21-22 carpet install, modify and install new sun visors   |                                      |
| <b>875</b>    | Friday 4-22-21 set up custom three point seat belt mounts, install more carpet, begin to rebuild seat bottoms, Ken  |                                      |
| <b>500</b>    | Monday 4-25-22, Ken build up seats, install new foam and recover, fit clips   |                                      |
| <b>875</b>    | 5/9/22 Monday, Ken, custom make new tunnel carpet, make custom seat belt mounting brackets, install seat belts  | completion of interior and headliner |
| <b>59.95</b>  | Custom tunnel carpet, binding   |                                      |
| <b>259.95</b> | seat belt set   |                                      |
|               | PARTS   |                                      |
| <b>589.99</b> | Carpet kit  |                                      |
| <b>899.95</b> | leather seat kit  |                                      |
| <b>779.95</b> | rear seat kit, leather  |                                      |
| <b>180</b>    | new foam for seat bases   |                                      |
| <b>138</b>    | foam for seat backs   |                                      |
| <b>45.98</b>  | new diaphragms for seats  |                                      |
| <b>25</b>     | hog rings   |                                      |
| <b>184.95</b> | headliner kit   |                                      |
| <b>329.95</b> | b pillar and new visors   |                                      |
| <b>30</b>     | glue  |                                      |
|               | MECHANICAL WORK   |                                      |
| <b>125</b>    | 5-10-22 Tucker, remove rear drums and front wheels, inspect underside, inspect wheel cylinders, uncover slave boot, slave shot, masters seem ok after removing cover to inspect, some wear in front end, herringbone brake soft hoses have to be updated, will replace, rear brake springs incorrectly installed, will replace, masters are both metal and dry, so no need to replace them with the plastic ones that are our only current option | mechanical service begins            |
| <b>149.95</b> | brake hoses, brake springs, rear wheel cylinders, shipping  |                                      |
| <b>718.75</b> | 5-11-22, Tucker, replace rear wheel cylinders, replace rear brake springs, adjust rear brakes, install drums, install new wheels, change slave cylinder, bleed entire system  |                                      |
| <b>16</b>     | hydraulic fluid   |                                      |

|                  |   |  |
|------------------|---|--|
|                  |   |  |
| <b>119.99</b>    | premium MGB slave cylinder  |  |
|                  |   |  |
| <b>562.50</b>    | 5-12-22, tucker, make new left side axle hard brake line, bend and flare, due to corrosion, retorque diff cover, flush and bleed brake system, finish rear brakes, put on drums, and wheels   |  |
| <b>20</b>        | brake line and fittings   |  |
|                  |   |  |
| <b>1000</b>      | 5-13-22 Friday, change plugs, change distributor, positive ground Pertronix, change oil filter and filter assembly Set timing, change transmission oil, valve adjust, set timing, extra time to repair spin on adaptor housing, remove and replace tachometer |  |
| <b>13.95</b>     | plugs   |  |
| <b>325</b>       | tachometer, correct original type wired to work with Pertronix  |  |
| <b>64.95</b>     | oil and filter, disposal  |  |
| <b>310.95</b>    | distributor, cap and wires (upgrade to pertronix)   |  |
| <b>46.99</b>     | coil  |  |
| <b>24</b>        | trans oil, 20-50, disposal  |  |
| <b>3.95</b>      | VC gasket   |  |
| <b>6</b>         | fan belt  |  |
|                  |   |  |
| <b>875</b>       | 5-16-22 change all water hoses, remove and replace oil cooler lines, change coolant, tune and synch carbs, remove pedal assembly and rebush to dramatically reduce lateral play in clutch pedal   |  |
| <b>43.95</b>     | MGB water hose set  |  |
| <b>66</b>        | oil cooler lines  |  |
| <b>14</b>        | coolant and recycling fee   |  |
| <b>8.95</b>      | new fuel filter   |  |
| <b>110</b>       | k and n air filter elements for MGB cans  |  |
| <b>2</b>         | electrical wire   |  |
| <b>10</b>        | clamps  |  |
| <b>6.95</b>      | thermostat and gasket   |  |
| <b>12</b>        | oil cooler grommets   |  |
|                  |   |  |
| <b>14961.75</b>  | total for parts and restoration   |  |
| <b>1140.13</b>   | sales tax 6.35%   |  |
|                  |   |  |
|                  | Non taxable items:  |  |
| <b>49.95</b>     | shipping of parts   |  |
| <b>225</b>       | Shipping inbound enclosed (came with AJS motorcycle)  |  |
| <b>225</b>       | Shipping home 5-27-22   |  |
|                  |   |  |
| <b>16601.83</b>  | total due   |  |
|                  | Payable to Empower LLC 59 North Harbor Street Branford CT 06405   |  |
| <b>-19594.83</b> | check 381 6-15-22   |  |
|                  | Thanks so much!   |  |