

ACTUAL



Bugeyeguys
59 N. Hwy 101 St
Bridgeton, NJ 08305
bugyeguys.com
203-68-0966
customer@bugyeguys.com



Gordon Goodwin
AN5L 45849

Automobile Restoration Build Sheet

	Mileage out on 2-2-24= 30 miles on new GPS speedo	
918.75	12-21-23 Terry strip accessories off the engine, disconnect the driveshaft, remove engine and transmission as a unit, strip front end	
1575	12-22-23 Terry clean grime and dirt out of engine bay, remove heater and battery, remove brake lines, clutch hard line and fuel lines, mount front A arms and spindles, remove and replace battery with proper battery and hold down,	
145	Battery	
18.49	Battery hold down kit	
343.98	Front a-arms	
2395.95	Disc brake kit	
579.95	Front shocks	
30	Front shock core shipping	
138	Fulcrum pin kits (x2 - a-arm bolts, shock bolts, a arm bushings, shock bushings, grease fittings, etc.)	
1531.25	12-26-23 Terry begin main wiring harness install, install switches and gauges in dash, begin installing LED kit in the car, wire up dummy regulator and customers fuse box, begin running brake & clutch hard lines	
41.99	Dip switch	
34.99	Dip switch harness	
494.95	Wiring harness	
377.95	GPS Speedometer	
272.95	Electric Tachometer	
39.98	Push/pull switches (2)	
14.99	H knob	
12.99	W knob	
26.95	Turn signal switch	
219.99	Ignition switch and guillotine	
12.99	Wiper motor mounting kit	
308.49	LED kit	
10.76	Rubber turn signal sockets (4)	
35.98	Dual filament bulb sockets (2)	
35.38	Single filament bulb sockets (2)	
69.95	Dummy regulator	
10.59	Brake light switch	
37.95	Choke cable	
37.95	Starter cable	
29.95	Starter switch	
18.95	Positive battery cable	



3.49	Starter solenoid boot	
59.99	Windshield washer pump	
264.99	Metal brake line kit	
48.95	Clutch hard line	
99.95	Slave cylinder	
215.99	3/4 master cylinder	
1575	12-27-23 Terry finish running brake/clutch hard lines, run new fuel lines & fuel pump, modified rear of 1275 engine to accept the oil seal conversion kit, mate 1275 engine & 5 speed transmission, modify flooring & shift tower to accept 5 speed, mount as a unit in the car	
8500	1275 Engine-A+ type	
5395	5 Speed Ford Transmission & clutch kit	
299.95	Modified shift lever	
39.95	5 Speed shift knob	
409.99	Aluminum flywheel	
23.94	Flywheel bolts	
8.49	Flywheel lock tab	
294.99	1275 rear oil seal conversion kit	
84.50	Oil pressure gauge line kit	
209.95	Fuel line kit with electric fuel pump	
1575	12-28-23 Terry modify our high torque starter as needed to get it to fit the engine properly, mount in car, install Pertronix distributor with new wires and a new coil, install and wire up alternator conversion kit, mount and plumb new hs2 carburetors, mount the header (swapped clients 948 header for a 1275 header), mount a new aluminum radiator and install all cooling hoses & system, install client provided rack boots	
279.95	High torque starter	
319.99	Pertronix distributor and wires	
48.99	Coil	
359.99	Alternator conversion kit	
11.99	Alternator bracket	
1599.95	New HS2 Carb set	
31.95	#3 Needles	
5.97	Carb springs	
17.99	Manifold mounting kit	
N/C	1275 Header (swapped clients 948 one)	
9.99	Throttle cable	
34.99	Ground Strap	
8.95	160 Thermostat and gasket	
28.99	Thermostat housing	



7.47	Thermostat studs & brass washers	
63.95	Heater valve kit	
329.95	Aluminum radiator	
45.50	Radiator hoses	
52.99	Copper heater pipe	
2.95	Valve cover gasket	
1575	12-29-23 Terry run/install rear wiring harness, install fuel system - new fuel tank & sending unit, install a new gas cap to mate to the new fuel tank, finish building up the front disc brakes, install a residual pressure valve in the master cylinder to have accurate rear brake actuation, bleed the hydraulic system, install the remainder of the exhaust system, install customers front coil springs	
365.95	Fuel Tank Kit with Sender installed	
69.99	Fuel tank pick up line	
19.99	Gas cap	
25.99	Residual pressure valve	
12.95	Brake fluid	
115	Center pipe	
369.95	Twin tip muffler	
39.95	Clamps and hangers	
1050	1-2-24 Terry fill car with fluids, wire nose, finish installing LED kit, install LED headlights and new housings, install sway bar kit, run and tune car, remove and replace rear shocks and dog bones, inspect rear brakes	
49.95	Engine oil	
57.9	Redline Transmission fluid	
29.95	Coolant	
149.95	H4 Headlight housings with LED bulbs	
299.95	Sway bar kit with painted brackets	
13.95	Spark plugs	
389.95	Rear shocks	
35	Shipping in shocks and cores out	
70	Dog Bones	
1400	1-3-24 Ken remove interior of car, strip seats, sandblast and paint top bar bow holders, sandblast and paint seat backs, bases, hoops and rails, started putting seats back together, modify seat backs to make covers tight.	
9.99	Paint	
1050	1-4-24 Ken cut out spongy floor on drivers side, fabricate new floor and frame pieces, welded them into place, seam sealed the welds under the car.	
9.95	Floor repair sheet metal	



962.5	1-5-24 Ken finished building seats, begin installing hardura flooring kit with a new panel kit	
419.95	Seat foams and squabs	
529.95	Red/white seat covers	
13.9	Seat clip kits	
10	Seat back custom poly backing strips	
23.95	Spray adhesive	
1137.5	1-8-24 Ken continue installing hardura flooring kit and panel kit, mount passengers seat in the car, install new seat slide spacers on the drivers floor board, replace the door seals	
999.95	Hardura flooring kit, red/red	
689.95	Deluxe panel kit with liners and upgraded door pockets	
104.95	Door seals	
39.95	Seat slide spacers	
23.95	Spray adhesive	
962.5	1-9-24 Ken remove windshield, drill out and tap broken windshield stanchion to frame screws, remove glass and replace, install new wipers, new three point seat belts, installed drivers seat	
269.99	Windshield glass	
84.99	Windshield glazing rubber and lock strip	
11.99	Windshield to body gasket	
10.99	Windshield post pads	
37.98	Wiper blades	
259.95	Red seat belts	
262.5	1-11-24 Terry lower rear end, replace differential drain plug, inspect pinion seal for leaks	
59.95	Rear axle lowering shims	
3.99	Differential drain plug	
612.5	11-15-24 Ken, remove bonnet and begin mounting front flip kit	
1400	11-16-24 Ken modify front flip bracketry to the nose will fit properly, weld- in x bracing and paint, fabricate custom single hole nose hold down straps in red to match rest of car.	
154.95	Front flip kit	
99.95	X bracing	
20	Paint	
65	Materials to make custom hold down straps	
875	11-17-24 Ken finish sewing the custom hold down straps and install them on the car, install a long tonneau, install a larger rear view mirror and stanchion mirrors	



424.95	Long tonneau	
34.99	Dash mirror	
79.95	Stanchion mirrors	
481.25	1-18-24 Ted remove rear springs to adjust spring height by adjusting leaves in spring, found rust in spring pocket - Ken to rectify rust	
1050	1-19-24 Kenny cut out spring bucket rust and prep	
1312.5	1-22-24 Ken welded up passengers side spring bucket and floor, welded up hole on drivers side next to spring bucket, put springs in the car and installed 6° shims to level out the car. Remove seat belt reel and shorten belts so they wind properly and don't flap out to hit the rocker panels.	
306.25	1-30-24 Nick Mount and balance tires + 1 used tire as spare	
919.96	Minilite wheels	
25	used tire for spare	
1100	Michelin XAS set of 4 tires	
16	Tire disposal fee	
12	Valve stems, lube, wheel weights	
175	1-31-24 Terry install the wheels on the car, adjust the steering, re-bleed the brakes, adjust the clutch action, install K&N filters	
249.95	K&N Air filters	
8.50	Brake fluid	
65	Nick - install rubber floor mats, parts and labor	
875	2-1-24 Terry Perform PDI - comprehensive check over to ensure vehicle is ready to depart our facility, run windshield washer hose, install a hanging gas pedal, remove left rear wheel, remove rear hub and press out studs, press in XL studs, re-install rear hub with spacers so wheel sits in proper location, rear axle is not quite centered in the back of the car so spacers were needed to get the new tires to fit properly on this side and this seems related to an old repair to the spring boxes. This is another reason why we had trouble lowering the rear end initially	
18.99	Washer hose	
55.95	Hanging gas pedal	
11.96	XL Studs (4)	
59.95	Wheel spacers	
87.5	2-1-24 Ted adjust idle, install customer's snorkel hose	



569.26	Shop supplies (solvent, rags, grease, welding supplies, etc.)	
57495.61	Subtotal of work completed to date	
-7500	Check # 3084 received	
-12500	Check # 3089 received 12/26/23	
-20000	Check # 3090 received 1/29/24	
1200	Enclosed Shipping from MN to CT (12/8/23)	
1500	Enclosed Shipping from CT to MN 2/2/24	
50	tire/rim transport surcharge	
20245.61	Balance due for work completed to date, including payments and shipping to and from CT.	
-20245.61	Check # 3091 received 2/19/24	
	** Heritage certificate ordered through Shopify on 1/22/24, will ship directly to Gordon's house	
	Make sure to check re-torque head bolts at 500 miles on your new engine.	
	General notes:	
	12--22-23 Phone call with GG approved all above upgrades & suggestions (TT) - brake lines, rear seal conversion, gauges and alternator, starter, led lights, led headlights	
	Thank you so much for entrusting us with your car!!!	